

Natasha and Eric McClure
1427 Edison Street
Detroit, MI 48206

Written narrative for HDC

1. Description of existing conditions (including a brief explanation of existing materials and their current condition at location of proposed work)

Our current front porch is just a cement block. The cement block has a few minor cracks and staining on it.

2. Description of project (including an explanation as to why replacement –rather than repair- is required)

We are not replacing our porch, but simply layering tile on top of it. This will help ensure that it is smoother if we want to step out and sit on our porch and will make it more level.

3. Detailed scope of proposed work for approval (formatted as bulleted list of all proposed exterior work to be approved and permitted) including, but not limited to:

The location: Front of the house, on the cement front porch

Quantity: Just one porch in front, roughly 15 ft wide

Tile installation, nothing else being replaced removed or built